

**2023 Power Unit Vs. Minimum Repair Spreadsheet**

Estimated Minimum Repair Costs Include 1 Hour of Field Labor but Do NOT Include Variable Associated Shipping Costs

Replacement Unit	Est. Min. Cost for Repair
<b>KASCO</b>	
<b><u>1/2HP</u></b>	
KA2400R/000	\$861.00 \$525.00
KA2400A/000	\$956.00 \$525.00
KA2400VX/000	\$1,114.00 \$525.00
<b><u>3/4HP</u></b>	
KA3400R/000	\$933.00 \$525.00
KA3400A/000	\$1,028.00 \$525.00
KA3400HR/000	\$952.00 \$525.00
KA3400VX/000	\$1,131.00 \$525.00
KA3400HVX/000	\$1,147.00 \$525.00
KA3400J/000	\$1,367.00 \$525.00
KA3400HJ/000	\$1,384.00 \$525.00
<b><u>1HP</u></b>	
KA4400R/000	\$1,150.00 \$525.00
KA4400A/000	\$1,196.00 \$525.00
KA4400HR/000	\$1,156.00 \$525.00
KA4400VX/000	\$1,433.00 \$525.00
KA4400HVX/000	\$1,439.00 \$525.00
KA4400J/000	\$1,678.00 \$525.00
KA4400HJ/000	\$1,691.00 \$525.00
<b><u>2HP</u></b>	
KA8400R/000	\$1,779.00 \$525.00
KA8400A/000	\$2,066.00 \$525.00
KA8400VX/000	\$2,937.00 \$525.00
KA8400J/000	\$2,943.00 \$525.00
KA2.3R/000	\$2,153.00 \$525.00
<b><u>3HP</u></b>	
KA3.1R/000	\$2,086.00 \$575.00
KA3.1A/000	\$2,635.00 \$575.00
KA3.1J/000	\$3,801.00 \$575.00
KA3.3R/000	\$2,377.00 \$575.00
<b><u>5HP</u></b>	
KA5.1R/000	\$2,696.00 \$625.00
KA5.1A/000	\$3,313.00 \$625.00
KA5.1VX/000	\$4,424.00 \$625.00
KA5.1J/000	\$4,698.00 \$625.00
KA5.3R/000	\$3,015.00 \$625.00
<b><u>7.5HP</u></b>	
KA7.3R/000	\$3,032.00 \$625.00

Replacement Unit	Est. Min. Cost for Repair
<b>AquaMaster</b>	
<b><u>1/2HP</u></b>	
AMR760003	\$1,838.00 \$650.00
AMR760151	\$1,838.00 \$650.00
<b><u>1HP</u></b>	
AMMR760038	\$3,164.00 \$675.00
AMMR760062	\$2,977.00 \$675.00
AMMR760078	\$3,071.00 \$675.00
AMMR760047	\$3,071.00 \$675.00
<b><u>2HP</u></b>	
AMMR760064	\$2,994.00 \$675.00
AMMR760068	\$3,104.00 \$675.00
AMMR760087	\$3,104.00 \$675.00
<b><u>3HP</u></b>	
AMMR760076	\$3,480.00 \$675.00
AMMR760070	\$3,180.00 \$675.00
AMMR760089	\$3,189.00 \$675.00
<b><u>5HP</u></b>	
AMMR760066	\$3,575.00 \$675.00
AMMR760072	\$3,308.00 \$675.00
AMMR760139	\$3,308.00 \$675.00
<b><u>7.5HP</u></b>	
AMMR760079	\$10,046.00 \$675.00
AMMR760080	\$8,956.00 \$675.00
AMMR760085	\$8,956.00 \$675.00

Replacement Unit	Est. Min. Cost for Repair
<b>Otterbine</b>	
<b><u>1/2HP</u></b>	
FO130001	\$1,638.00 \$575.00
FO130002	\$1,640.00 \$575.00
FO130003	\$1,672.00 \$575.00
FO130004	\$1,674.00 \$575.00
<b><u>1HP</u></b>	
FO160100116	\$2,690.00 \$725.00
FO160100216	\$2,690.00 \$725.00
<b><u>2HP</u></b>	
FO160200216	\$2,625.00 \$725.00
<b><u>3HP</u></b>	
FO160300216	\$3,545.00 \$725.00
FO160300236	\$3,545.00 \$725.00
FO160300336	\$3,545.00 \$725.00
FO160300436	\$3,395.00 \$725.00
<b><u>5HP</u></b>	
FO160500216	\$4,048.00 \$725.00
FO160500236	\$3,918.00 \$725.00
FO160500336	\$3,918.00 \$725.00
FO160500436	\$3,918.00 \$725.00
<b><u>7.5HP</u></b>	
	N/A N/A